ECS Configurati	ion Char	nge ique	st				Ρ	age 1 of	1	Pages	
CCR No. 98-	406	Logged Da	ite 04	4-01-98	Rev.	-	Request Ty	/pe C	CCR		
Priority Routine	· 🗀 '	Urgent 🗌	Emerge	ency X	Affected	Release	В	Change	Class	IN	
Title (description) To configure "Portugal" for DMS Subsystem. EIN#0688											
Documents Affected Source Nos (RID, NCR, Action Item, GSFC CCR, etc.) or											
N/A						N/A					
RTM Change Start New Baseline											
Problem DMS has received a no	ew Sun 20/5	50 that needs to	o be instal	led on the 4	8 network.						
Proposed Solution Install on Rack D5 to replace "CEOS1" location. Push in DNS "Portugal" and install on the 48 network. Configure "Portugal" with the SUN OS 5.5.1, Clearcase 3.1.1 and the current patches baseline for both COTS.											
Import Analysis.											
Impact Analysis: Organizations Affected:		воо П	Contracts		CC Chief Coa T	 1	FOC .		1400 F	_ }	
Procurement	, 1	∞ □	Contracts Rel. Dev	_	CS Chief Eng [-	FOS Rel. C	SCDC	M&O [_ ,	
Science Off	Sec	curity 🔲	Subcontrot		Rel. A [Sys. Eng [\exists	Sys Verf Acpt	SCDC	Arch.	- <u> </u>	
Cost:	١	None X	Small (Not exceedi	ng \$100,000)	Medium [(\$100,000 to \$50))0.000)	Large (Over \$500,000)		•••••••••••	,,,,,,	
Schedule:		None X	C	ther			Need by date	: 04/06/98			
Additional LOC						Man-Months					
Materials				///		1	. ,				
Originator Michelle D. Johnson Michelle L. Johnson Michelle L. Johnson											
Office Development	Office	Manager	Signature Signature	-, 50	Turk	7	3/31/78	/	Date		
Disposition	Approved	d [7]	Approved	d w/Comm	ent 🗍	Forwa	rd 🗍	Disappro	ved [$\neg \neg$	
Comments:							<u>-</u>		_	_	
	CCB Chai	rperson	Wa.	DA.	Comet	2		4/1	198		

ORIGINAL

CM010C96

ECS